HANGZHOU REMEMBER FABRIC CO. LTD
#888CHONGCHAO RD,CHONGXIAN TOWNM,LINPING DISTRIT HANGZHOU CHINA

Sample Description	:	FABRIC
Style No.	:	YB-6765
Item No.	:	RC01010437
SKU No.	:	RC01010437
P.O. / Ref. No.	:	PO000000339
Buyer	:	HANG ZHOU YI BEI FURNITURE CO., LTD
Manufacturer	:	HANGZHOU REMEMBER FABRIC CO. LTD
Country of Destination	:	CANADA,UNITED STATES

As above test item and its relevant information regarding to the submission are provided and confirmed by the applicant. SGS is not liable to either the test item or its relevant information, in terms of the accuracy, suitability, reliability or/and integrity accordingly.

****

SGS Ref No.	:	T525103304735N
Sample Receiving Date	:	Aug 18, 2025
Test Performing Date	:	Aug 18, 2025 to Aug 26, 2025
Test Performed	:	Selected test(s) as requested by applicant
Test Result(s)	:	For further details, please refer to the following page(s)

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co., Ltd. Shunde Branch

Marco Leung
Authorized Signatory

Scan to see the report
SDHL250801452901FT
Verification:
check.sgsonline.com.cn

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shunhe South Road, Wusha, Daliang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805888 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居民委员会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805888 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Test Result Summary

No.	Test(s) Requested	Result(s)	Comments
1	Client's requirement - Color Fastness to Light (AATCC TM16.3-2020)	PASS	/
2	Client's requirement - Colour Fastness to Crocking (AATCC TM8-2016e(2022)e)	PASS	/
3	Per client requested, with reference to ASTM D1424-21, Tearing Strength of Fabrics by Falling-Pendulum (Elmendorf-Type) Apparatus	PASS	/
4	Per client requested, with reference to ASTM D1683 /D1683M-22 Failure in Sewn Seams of Woven Fabrics	SEE RESULT	/
5	Per client requested, with reference to ASTM D5034-21 Breaking Strength and Elongation of Textile Fabrics （Grab test）-Tensile strength	PASS	/
6	Pilling Resistance and Other Related Surface Changes of Textile Fabrics: Random Tumble Pilling Tester (ASTM D3512/D3512M-22)	PASS	/
7	Abrasion Resistance of Textile Fabrics (Oscillatory Cylinder Method) – ASTM D4157-13(Reapproved 2022)	SEE RESULT	/
For further details, please refer to the following page(s)			

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shunhe South Road, Wusha, Daliang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805888 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居民委员会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805888 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Results:

Color Fastness to Light
(AATCC TM16.3-2020; Option 3; Xenon Arc Lamp)

	1	Client's Requirement
After 40 AFU		
Change in shade	4.5	Min.4.0

Remark: Grey Scale Rating is based on the 5-step scale of 1 to 5, where 1 is bad and 5 is good.

Specimen Description:
1. A

Color Fastness to Crocking
(AATCC TM8-2016e(2022)e; Size of crocking finger: 16mm diameter)

	1	Client's Requirement
Dry staining	4.5	Min.4.0
Wet staining	4.5	Min.3.0

Remark: Grey Scale Rating is based on the 5-step scale of 1 to 5, where 1 is bad and 5 is good.

Specimen Description:
1. A

Tearing Strength
(ASTM D1424-21; Elmendorf)

Test Result:

	Unit	A	Requirement
Warp/Length Yarns Torn	lbf	>28.8#	Min.10
Weft/Width Yarns Torn	lbf	>28.8#	Min.10

Remark: #=Exceed instrument range

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shunhe South Road, Wusha, Dailang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805888 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居民委员会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805888 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Seam Strength
(Refer to ASTM D1683/D1683M-22, Procedure A)

Test Result:
Seam strength

	Unit	A	Requirement
Warp // Seam	lbf	117.3STB	-
Weft // Seam	lbf	99.2STB	-

Seam Slippage

	Unit	A	Requirement
SO¼ in Warp // Seam	lbf	STB at 117.3#	Min.25
SO¼ in Weft // Seam	lbf	STB at 99.2#	Min.25

Remark:
S.T.B. = Sewing Thread Break
SO ¼ in= Seam opening at ¼ inch
= Before 1/4 inch opening

Tensile Strength
(ASTM D5034-21; Grab method)

Test Result:

	Unit	A	Requirement
Warp/Length	lbf	249.7	Min.50
Weft/Width	lbf	230.7	Min.50

检验检测专用章 Inspection & Testing Services
SGS-CSTC Standards Technical Services Co., Ltd. Shunde Branch Foshan

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shunhe South Road, Wusha, Daliang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805888 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居民委员会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805888 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Pilling/Fuzzing Resistance
(ASTM D3512/D3512M-22; Random Tumble Pilling Tester)

As received
30 min

Sample	A	Requirement
Pilling Rating	4.5	Min.3.0
Fuzzing Rating	4.5	Min.3.0

60min

Sample	A	Requirement
Pilling Rating	4.5	Min.3.0
Fuzzing Rating	4.5	Min.3.0

Remark:

Nomenclature for pilling rating:
5—no pilling
4—slight pilling
3—moderate pilling
2—severe pilling
1—very severe pilling

Nomenclature for fuzzing rating:
5—no fuzzing
4—slight fuzzing
3—moderate fuzzing
2—severe fuzzing
1—very severe fuzzing

Abrasion Resistance of Textile Fabrics (Oscillatory Cylinder Method)
[ASTM D4157-13(Reapproved 2022), Option 1]

Test condition:
Abradant: #10 Cotton Duck
Head Pressure: 3lbf
Specimen Tension: 4lbf


Result:

Sample:		A	
Specimen direction	Unit	Length/Warp	Width/Weft
Result	Cycles	>20000	>20000

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shunhe South Road, Wusha, Dailang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805888 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居民委员会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805888 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

Sample Picture (As received)

Pic.1



Remark: This test was subcontracted to SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch Testing Center.

End of Report

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
1-2/F., Building 1, European Industrial Park, No.1, Shunhe South Road, Wusha, Daliang, Shunde District, Foshan, Guangdong, China 528300 t (86-757)22805888 www.sgsgroup.com.cn
中国·广东·佛山市顺德区大良街道办事处五沙社区居民委员会顺和南路1号欧洲工业园一号厂房首层、二层 邮编: 528300 t (86-757)22805888 sgs.china@sgs.com